
# PRISM

Thanks to its highly durable PC frame, the PRISM model offers excellent protection as well as great value for money.









1614402 • Smoke Lens



1614403 • Silver Flash Lens



1614404 • Bronze Lens



1614406 • Amber Lens



- **+ ULTRA LIGHT WEIGHT & RIMLESS POLYCARBONATE FRAME**
- **+** SINGLE PIECE 8 BASE, DISTORTION FREE LENS
- **+** FULLY RECYCLABLE: ALL POLYCARBONATE FRAME **WITH NO METAL PARTS**



# PRISM

MODEL	VERSIONS	PRODUCT CODE	LENS MARKING	FRAME MARKING	COATINGS
PRISM	Clear	1614401	Ю	AS/NZS 1337.1.2010	Anti-scratch/Anti-fog
	Smoke	1614402	13	AS/NZS 1337.1.2010	Anti-scratch/Anti-fog
	Silver Flash	1614403	12	AS/NZS 1337.1.2010	Hard coat
	Bronze	1614404	13	AS/NZS 1337.1.2010	Anti-scratch/Anti-fog
	Amber	1614406	Ю	AS/NZS 1337.1.2010	Anti-scratch/Anti-fog

### LENS MARKING

- 1. The letter 'I' signifies 'Medium Impact' approval.
- O. The letter 'O' marking signifies that the product has been approved for the use both outdoors and indoors and the terminology used by Australian standards is 'outdoor un-tinted'. This marking appears on all clear, amber and contrast lenses

### **OCULAR LENS CATEGORY:**

- O. Range of luminous transmittance 80-100% (clear & amber).
- 2. Range of luminous transmittance 18-43% (flash).
- 3. Range of luminous transmittance 8 -18% (smoke & bronze).

# **APPLICATIONS**

- Driving
- Solar UV exposure
- Emergency response
- Rigging
- Assembly and production work

# MAIN MARKETS

- Manufacturing
- Petrochemical
- Construction
- Government
- Mining
- Medical and dental
- Food industry

### LENSES

- 2mm polycarbonate
- 8 base curve
- 'ALS' anti-fog/anti-scratch coating on both sides of lens: Clear, Smoke, Bronze and Amber
- Hard coating on Silver Flash lens
- 100% UV 385 Clear
- 100% UV 400 Smoke, Silver Flash, Bronze and Amber

## CLEANING AND STORAGE

**CLEANING:** Bollé Safety recommends only using our **OCLEAN** Lens cleaning system.

**MAINTENANCE:** Pitted, scratched or damaged lenses must be replaced by replacing the complete product. If the frame is damaged also replace the complete product. After each use it is recommended to keep the spectacles or goggles in a microfiber pouch or rigid case.

STORAGE: Store between 5 and 40 °, humidity <90%.

CHARACTERISTICS				
LENSES	PC - 2,2 mm - Curve 8			
FRAME	PC			
TEMPLES	PC			
STRAP	Non applicable			
FOAM	Non applicable			
SPARE LENSES	No			

# FRAME MARKING

**AS/NZS 1337.1.2010**: Tested and approved to AS/NZS 1337.1.2010 for medium impact protection. Resists a 6mm at 45 m/s.

Available from



