
# ULTIMATE RESISTANCE

The most advanced protection for extreme work environments (cold/hot/dust/humid environments/oil & gas industries, mining...). ULTIM8 offers maximum resistance to fogging thanks to PLATINUM® coating.



- + TEMPLE/GOGGLES TRANSFORMATION KIT



# ULTIMATE RESISTANCE

MODEL	VERSIONS	REFERENCES	LENS MARKING	FRAME MARKING	COATINGS
ULTIM8	Clear	ULTIPSI	Ю	AS/NZS 1337.1.2010	Anti–scratch/Anti–fog/*₽

## LENS MARKING

- Platinum is a permanent coating applied on both sides of the lens that gives a high resistance to scratching (1.4 cd / m<sup>2</sup>) and to the most aggressive chemicals and delays the onset of fogging for two minutes, as per the testing requirements of EN166.
- I. The letter 'I' signifies 'Medium Impact' approval.
- **O.** The letter 'O' signifies that the product has been approved for the use both outdoors and indoors, and the terminology used by Australian standards is 'outdoor un–tinted'. This marking appears on all clear, amber and contrast lenses.

## Ocular lens category:

**O.** Range of luminous transmittance 80–100% (Clear).

## TECHNOLOGIES

### 

The new exclusive scratch and fog resistant coating K and N certified **PLATINUM®** guarantees even more safety, reliability and comfort. Washable (water and soap), this permanent coating applied on both sides of the lens makes it highly scratch-resistant and effectively delays the appearance of fogging.

## LENSES

- 2mm polycarbonate
- Platinum coating on both sides of Clear
- 100% UV 385 Clear

## FRAME MARKING

**AS/NZS 1337.1.2010**: Tested and approved to AS/NZS 1337.1.2010 – Medium Impact protection. Meets the requirement of splash approval when used with the supplied head strap correctly adjusted.

## CLEANING AND STORAGE

**CLEANING**: The lenses should be cleaned regularly. Bollé Safety recommends only using the B–clean lens cleaning system.

**MAINTENANCE:** Pitted, scratched or damaged lenses must be replaced by replacing the complete product. If the frame is damaged also replace the complete product. After each use it is recommended to keep the spectacles or goggles in a microfiber pouch or rigid case.

STORAGE: All products must be stored in a dry and clean environment.

CHARACTERISTICS				
LENSES	PC – 2,2 mm – Curve 8			
STRAP	15mm adjustable – Polyester			
FOAM	TPR			





22/05/2018